

- Water-soluble solvents dissolve grease and grime.
- o Alkalis and surfactants loosen and remove stubborn dirt and grime.

How to use

- Mix 1 part product with 5 parts water (1:5).
- Wet down surrounding painted surface with cool water.
- Generously spray engine and allow to dwell for several minutes.
- Thoroughly pressure rinse, standing at different angles.

Notes

- Do NOT swallow.
- Use Gloves and Goggles as a precautionary measure.